

- 2. ALL AREAS WHERE LOOP WIRES ARE TO PLACED SHALL HAVE A UNIFORM DEPTH AND SMOOTHNESS.
- 3. LOOP SEALANT SHALL BE CRAFCO MSI 34271. APPLY PER MANUFACTURERS RECOMMENDATIONS.

APPROVED: PAUL CHO

REV. DATE: AUGUST 25, 1999

TRANSPORTATION DIVISION





STANDARD DETAILS

LOOP DETECTOR SLOT

FILE SD411.DWG DRAWING NO. 411